


## PITCH GAUGE

### SERIES 921



- ◆ Measure the pitch of thread
- ◆ Accuracy:  $\pm 0.07\text{mm}$



921-020-12

| Code       | Range   | Thread  | Quantity | Leaves pitch(mm)  |
|------------|---------|---------|----------|---|
| 921-020-12 | 2-20mm  | Tr30°   | 12       | 2, 3, 4, 5, 6, 7, 8, 9, 10, 12, 16, 20mm                                |
| 921-012-16 | 1-12TPI | ACME29° | 16       | 1, 1-1/3, 1-1/2, 1-3/4, 2, 2-1/2, 3, 3-1/2, 4, 5, 6, 7, 8, 9, 10, 12TPI |


## CENTER GAUGE

### SERIES 926



926-060-02

- ◆ Check the screw angle and pitch
- ◆ Accuracy:  $\pm 30'$



| Code       | Screw type    | Angle( $\alpha$ ) | Graduation  |
|------------|---------------|-------------------|---|
| 926-060-01 | metric 60°    | 60°               | 0.5mm and 1mm   |
| 926-060-02 | unified 60°   | 60°               | front side: 1/14" and 1/20",<br>reverse side: 1/24" and 1/32" |
| 926-055-01 | whitworth 55° | 55°               | front side: 1/14" and 1/20",<br>reverse side: 1/24" and 1/32" |


## THREAD GAUGE

### SERIES 927




927-008-01

- ◆ To check and set screw cutting tools
- ◆ Angle accuracy:  $\pm 10\text{min}$ .



927-008-01



927-012-01

| Code       | Range   | Thread type | Pitch  |
|------------|---------|-------------|--|
| 927-008-01 | 1-10TPI | ACME 29°    | 1, 1-1/3, 1-1/2, 1-3/4, 2, 2-1/2, 3, 4, 5, 6, 7, 8, 9, 10TPI |
| 927-012-01 | 2-12mm  | Tr30°       | 2, 3, 4, 5, 6, 7, 8, 9, 10, 12mm                             |